City of Lewiston Vault Inventory/Assessment

Date: July 6, 2016	6						
ddress: 800 Main St.							
Owner/Business: Gary Rencehausen / Mill			ll End Building				
Property Line Known:		Investigation Needed:					
Assessment Team:							
Kris Brown			David Witthaus, Photographer				
Michelle Bly							
Jennife	er Blood						
Vault No: B							
Access: Door							
Access Opening Dimensions	Feet	Inches	Vault Dimensions	Feet	Inches		
Width	3	0	Width	14	1		
Height	7	0	Depth	11	11		
			Height (to bottom of beam)	8	8		
Beams	Feet	Inches	Sidewalk Vault Opening Dimensions	Feet	Inches		
Number of Beams		4	Width				
Width (flange)		4.75	Depth				
Depth			Height				
Height			None Visible				
Spacing (on center)							
Left Side Wall: Material: Other			If Other: Wood partiti	ion wall			
Condition:							
Comments: N/A not a v	ault wall						

City of Lewiston Vault Inventory/Assessment

Condition: Fa	Stone	If Other:				
	air					
Comments: Pa						
	Painted or plastered over. Concrete in	fill at top of wa	all. Past evidence of dampness			
(possibly from	N Vault A), but rained the night before	the assesmer	nt and no signs of current dampness.			
Street Walls:						
Material: St	Stone	If Other:				
Condition: Po	Poor					
Comments: Po	Comments: Poor to fair condition. Loose unmortared stone at top of wall.					
Building Wall	ls:					
Material: O	Other	If Other:	Drywall partition wall			
Condition:						
Comments: N/A- condition of partition wall. Stone pilaster in good condition.						
Flooring:						
Material: C	Concrete	If Other:				
Condition: G	Good					
Comments:						
Ceiling:						
Material: <u>C</u>	Concrete	If Other:	Covered with tar paper			
Condition: U	Jnknown					
Comments: Cannot evaluate condition due to tar paper.						
Comments: Ceiling: Material: Condition: U	Concrete		Covered with tar paper			

City of Lewiston Vault Inventory/Assessment

Sidewalk:					
Material:	Concrete	If Other:			
Condition:	Poor				
Comments:	76.5 ft crack up to 1" wide. East 30%	fair to poor condition, remaining in fair condition.			
Beams:					
Material:	Steel	If Other:			
Condition:	Fair				
Comments: Mildly corroded. More corrosion street side.					
Schematic(s) Attached: Yes					
Current Use	e of Vault: Empty				
Historic Val	ue of Vault: See independent assess	ment			
Overall Rating:					
At Time of I	nventory: Fair				
After Completion of All Inventories: Fair					
Additional Comments:					
If the concrete ceiling was not covered, rating could possibly be 'good', but beams are corroded					
at street side bearing.					

This rating is based on visual observations of the various components of the vault including materials, conditions, etc. However, no structural analysis was performed, and the rating is not intended to indicate the structural integrity of the vault or sidewalk above.