

**City of Lewiston**  
**Vault Inventory/Assessment**

Date: June 30, 2016

Address: 842 Main St.

Owner/Business: JMS

Property Line Known: \_\_\_\_\_ Investigation Needed: \_\_\_\_\_

Assessment Team:

Kris Brown David Witthaus, Photographer

Michelle Bly \_\_\_\_\_

\_\_\_\_\_

**Vault No:** Filled in

**Access:** \_\_\_\_\_

<b>Access Opening Dimensions</b>	<b>Feet</b>	<b>Inches</b>
Width	--	--
Height	--	--

<b>Vault Dimensions</b>	<b>Feet</b>	<b>Inches</b>
Width	--	--
Depth	--	--
Height (to bottom of beam)	--	--

<b>Beams</b>	<b>Feet</b>	<b>Inches</b>
Number of Beams	--	
Width (flange)	--	--
Depth	--	--
Height	--	--
Spacing (on center)	--	--

<b>Sidewalk Vault Opening Dimensions</b>	<b>Feet</b>	<b>Inches</b>
Width	--	--
Depth	--	--
Height	--	--

**Left Side Wall:**

Material: \_\_\_\_\_ If Other: \_\_\_\_\_

Condition: \_\_\_\_\_

Comments: \_\_\_\_\_

\_\_\_\_\_

**City of Lewiston  
Vault Inventory/Assessment**

**Right Side Wall:**

Material: \_\_\_\_\_ If Other: \_\_\_\_\_

Condition: \_\_\_\_\_

Comments: \_\_\_\_\_

---

**Street Walls:**

Material: \_\_\_\_\_ If Other: \_\_\_\_\_

Condition: \_\_\_\_\_

Comments: \_\_\_\_\_

---

**Building Walls:**

Material: \_\_\_\_\_ If Other: \_\_\_\_\_

Condition: \_\_\_\_\_

Comments: \_\_\_\_\_

---

**Flooring:**

Material: \_\_\_\_\_ If Other: \_\_\_\_\_

Condition: \_\_\_\_\_

Comments: \_\_\_\_\_

---

**Ceiling:**

Material: \_\_\_\_\_ If Other: \_\_\_\_\_

Condition: \_\_\_\_\_

Comments: \_\_\_\_\_

---

**City of Lewiston  
Vault Inventory/Assessment**

**Sidewalk:**

Material: \_\_\_\_\_ If Other: \_\_\_\_\_

Condition: \_\_\_\_\_

Comments: \_\_\_\_\_

**Beams:**

Material: \_\_\_\_\_ If Other: \_\_\_\_\_

Condition: \_\_\_\_\_

Comments: \_\_\_\_\_

Schematic(s) Attached: No

Current Use of Vault: Filled in

Historic Value of Vault: See independent assessment

**Overall Rating:**

At Time of Inventory: N/A

After Completion of All Inventories: N/A

**Additional Comments:**

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**This rating is based on visual observations of the various components of the vault including materials, conditions, etc. However, no structural analysis was performed, and the rating is not intended to indicate the structural integrity of the vault or sidewalk above.**