

**City of Lewiston  
Vault Inventory/Assessment**

Date: June 7, 2016

Address: 311 Main Street

Owner/Business: Vikki Ross / Bojack's Broiler Pit

Property Line Known: \_\_\_\_\_ Investigation Needed: \_\_\_\_\_

Assessment Team:

Kris Brown

David Witthaus, Photographer

Gwen Ellis

**Vault No:** A (kitchen and cooler)

**Access:** Open

framed entry way

<b>Access Opening Dimensions</b>	Feet	Inches
Width	3	0
Depth	--	--
Height	6	2

<b>Vault Dimensions</b>	Feet	Inches
Width	22	6
Depth	8	9
Height	6	6

<b>Building Side</b>	Feet	Inches
Width	--	--
Depth	--	--
Height	--	--

<b>Street Side</b>	Feet	Inches
Width	--	--
Depth	--	--
Height	--	--

<b>Beams</b>	Feet	Inches
Number of Beams	Not visible	
Width (flange)	--	--
Depth	--	--
Height	--	--
Spacing (on center)	--	--

<b>Sidewalk Vault Opening Dimensions</b>	Feet	Inches
Width	2	8
Depth	--	--
Height	6	2

(door to street)

**Left Side Wall:**

Material: Unknown

If Other: Various wall coverings

Condition: Unknown

Comments: Cannot view original walls or ceiling. Covered with sheet rock

**City of Lewiston  
Vault Inventory/Assessment**

**Right Side Wall:**

Material: Unknown If Other: Various wall coverings

Condition: Unknown

Comments: Cannot view original walls or ceiling. Covered with sheet rock. Cooler on right side wall with 6' width

**Street Walls:**

Material: Unknown If Other: Covered

Condition: Unknown

Comments: \_\_\_\_\_

**Building Walls:**

Material: Stone If Other: Covered

Condition: Unknown

Comments: Small portion of stone visible. Not enough to make determination of condition

**Flooring:**

Material: Unknown If Other: Covered with vinyl tile

Condition: Unknown

Comments: 1'x1'

**Ceiling:**

Material: \_\_\_\_\_ If Other: Covered

Condition: Unknown

Comments: \_\_\_\_\_

**City of Lewiston  
Vault Inventory/Assessment**

**Sidewalk:**

Material: Concrete If Other: \_\_\_\_\_

Condition: Fair

Comments: 5-1/2" thick. 2' Diameter opening visible from street. Steel/concrete manhole with glass.  
4' x 2'-6" rectangular opening Concrete with glass

**Beams:**

Material: Unknown If Other: \_\_\_\_\_

Condition: Unknown

Comments: not visible

Schematic(s) Attached: Yes

Current Use of Vault: See independent assessment

Historic Value of Vault: By others

**Overall Rating:**

At Time of Inventory: Unknown

After Completion of All Inventories: Unknown

**Additional Comments:**

Unable to determine rating due to lack of visibility or accessibility.

**This rating is based on visual observations of the various components of the vault including materials, conditions, etc. However, no structural analysis was performed, and the rating is not intended to indicate the structural integrity of the vault or sidewalk above**