

**City of Lewiston
Vault Inventory/Assessment**

Date: June 10, 2016

Address: 300 Main Street

Owner/Business: YWCA

Property Line Known: _____ Investigation Needed: _____

Assessment Team:

Michelle Bly

David Witthaus, Photographer

Kris Brown

Gwen Ellis

Vault No: Filled in per Mike, maintenance staff. Completed visual inspection to verify.

Access: _____

Access Opening Dimensions	Feet	Inches
Width	--	--
Height	--	--

Vault Dimensions	Feet	Inches
Width	--	--
Depth	--	--
Height (to bottom of beam)	--	--

Beams	Feet	Inches
Number of Beams	--	
Width (flange)	--	--
Depth	--	--
Height	--	--
Spacing (on center)	--	--

Sidewalk Vault Opening Dimensions	Feet	Inches
Width	--	--
Depth	--	--
Height	--	--

Left Side Wall:

Material: _____

If Other: _____

Condition: _____

Comments: _____

**City of Lewiston
Vault Inventory/Assessment**

Right Side Wall:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Street Walls:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Building Walls:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Flooring:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Ceiling:

Material: _____ If Other: _____

Condition: _____

Comments: _____

**City of Lewiston
Vault Inventory/Assessment**

Sidewalk:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Beams:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Schematic(s) Attached: No

Current Use of Vault: Filled in

Historic Value of Vault: See independent assessment

Overall Rating:

At Time of Inventory: N/A

After Completion of All Inventories: N/A

Additional Comments:

This rating is based on visual observations of the various components of the vault including materials, conditions, etc. However, no structural analysis was performed, and the rating is not intended to indicate the structural integrity of the vault or sidewalk above.