

From: Courtney Kramer
Executive Director, Beautiful Downtown Lewiston

To: TD&H Engineering

Summary:

Nicely preserved vault continues to convey the original design of the space. Loss of access to the sidewalk and the prismatic glass detrimental to retention of the vault's historic integrity.

Property Address: 326 Main Street, Vault A (Wild at Art)

Determination of Historic Significance: Low historic significance

Historic Significance		
	Determination	Comments
Is the building listed or eligible for listing on the National Register of Historic Places?	Yes	
Did the vault provide space essential to the functioning of the business or use in the building?	No	
Historic Integrity		
Location	Yes	
Design	No	
Access to sidewalk?	No	
Setting	Yes	
Materials	Yes	
Prismatic glass?	No	
Workmanship	Yes	Original ceiling has been covered with a stucco (?) material which still conveys the form of the ceiling though the original materials are obscured.
Original ceiling?	Yes	
Feeling	No	
Association	No	