

**City of Lewiston
Vault Inventory/Assessment**

Date: June 20, 2016

Address: 704 Main Street

Owner/Business: Mike Haines / Old Kling's Building

Property Line Known: _____ Investigation Needed: _____

Assessment Team:

Michelle Bly

David Witthaus, Photographer

Kris Brown

Vault No: _____

Access: None

Access Opening Dimensions	Feet	Inches
Width		
Height		

Vault Dimensions	Feet	Inches
Width		
Depth		
Height (to bottom of beam)		

Beams	Feet	Inches
Number of Beams		
Width (flange)		
Depth		
Height		
Spacing (on center)		

Sidewalk Vault Opening Dimensions	Feet	Inches
Width		
Depth		
Height		

Left Side Wall:

Material: _____

If Other: _____

Condition: _____

Comments: _____

**City of Lewiston
Vault Inventory/Assessment**

Right Side Wall:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Street Walls:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Building Walls:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Flooring:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Ceiling:

Material: _____ If Other: _____

Condition: _____

Comments: _____

**City of Lewiston
Vault Inventory/Assessment**

Sidewalk:

Material: Concrete If Other: _____

Condition: Good

Comments: 13" x 17" checkered plate. May be access to utility meter

Beams:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Schematic(s) Attached: No

Current Use of Vault: N/A

Historic Value of Vault: See independent assessment.

Overall Rating:

At Time of Inventory: N/A

After Completion of All Inventories: N/A

Additional Comments:

No vault access from inside. Newer concrete wall poured with no access.

This rating is based on visual observations of the various components of the vault including materials, conditions, etc. However, no structural analysis was performed, and the rating is not intended to indicate the structural integrity of the vault or sidewalk above.