

From: Courtney Kramer
 Executive Director, Beautiful Downtown Lewiston

To: TD&H Engineering

Summary:

Part of the extraordinary vault complex wrapping from 6th to Main at 826-830 Main Street. Vault was accessed from stairs on 6th and clearly served a function to businesses in the building, as evidenced by presence of finished materials in the space.

Property Address: 826 Main St 6th side vault A

Determination of Historic Significance: High historic significance

Historic Significance		
	Determination	Comments
Is the building listed or eligible for listing on the National Register of Historic Places?	Yes	
Did the vault provide space essential to the functioning of the business or use in the building?	Yes	Existence of stucco over the stone walls indicates more than a basic utilitarian function of the space. What was it used for?
Historic Integrity		
Location	Yes	
Design	Yes	
Access to sidewalk?	Yes	
Setting	Yes	
Materials	Yes	This vault appears to be of later construction, with original plaster over stone vault walls. Prismatic glass still functional.
Prismatic glass?	Yes	
Workmanship	Yes	
Original ceiling?	Yes	
Feeling	Yes	
Association	Yes	