From: Courtney Kramer

Executive Director, Beautiful Downtown Lewiston

To: TD&H Engineering

Summary:

Well preserved vault. Loss of prismatic glass and sidewalk access detrimental to the vault's historic integrity. A more in-depth history of this vault would explain the space's unusual layout and function. Presence of specialized building materials, like the big metal tub, speaks to the function this vault played in a business in the space.

Property Address: 832 Main Street

Determination of Historic Significance: High historic significance

Historic Significance		
	Determination	Comments
Is the building listed or eligible for listing on the National Register of Historic Places?	Yes	
Did the vault provide space essential to the functioning of the business or use in the building?	Yes	Evidence of finish work, including trim and tools for a business in the vault. What is the big metal tub for?
Historic Integrity		
Location	Yes	
Design	Yes	
Access to sidewalk?	No	
Setting	Yes	
Materials	Yes	
Prismatic glass?	No	
Workmanship	Yes	
Original ceiling?	Yes	
Feeling	No	No access to exterior, no prismatic glass.
Association	Yes	