

**City of Lewiston
Vault Inventory/Assessment**

Date: June 30, 2016

Address: 844 Main St.

Owner/Business: JMS Limited Partnership / Barber Shop

Property Line Known: _____ Investigation Needed: _____

Assessment Team:

Kris Brown

David Witthaus, Photographer

Michelle Bly

Jennifer Blood

Vault No: Filled in with concrete (no photo, common basement with 842 Main St.)

Access: None

Access Opening Dimensions	Feet	Inches
Width	--	--
Height	--	--

Vault Dimensions	Feet	Inches
Width	--	--
Depth	--	--
Height (to bottom of beam)	--	--

Beams	Feet	Inches
Number of Beams	--	
Width (flange)	--	--
Depth	--	--
Height	--	--
Spacing (on center)	--	--

Sidewalk Vault Opening Dimensions	Feet	Inches
Width	--	--
Depth	--	--
Height	--	--

Left Side Wall:

Material: _____

If Other: _____

Condition: _____

Comments: _____

**City of Lewiston
Vault Inventory/Assessment**

Right Side Wall:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Street Walls:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Building Walls:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Flooring:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Ceiling:

Material: _____ If Other: _____

Condition: _____

Comments: _____

**City of Lewiston
Vault Inventory/Assessment**

Sidewalk:

Material: Concrete If Other: _____

Condition: Good

Comments: _____

Beams:

Material: _____ If Other: _____

Condition: _____

Comments: _____

Schematic(s) Attached: No

Current Use of Vault: N/A- Filled in.

Historic Value of Vault: See independent assessment

Overall Rating:

At Time of Inventory: N/A

After Completion of All Inventories: N/A

Additional Comments:

This rating is based on visual observations of the various components of the vault including materials, conditions, etc. However, no structural analysis was performed, and the rating is not intended to indicate the structural integrity of the vault or sidewalk above.